

# EXPORTING TEST RESULTS

1. Go to **Export**→**PDF** to export selected test report in \*.PDF format.



Go to **Export**→**CSV** to export selected test report in \*.CSV format.



- Summary – Generates summarised result(s) listing only the basic information. Generally used to tabulate report for entire project.

## Summary Report




Cable Label	Limit	Result	Length (m)	Margin (dB)	Factory Calibration Status	Date & Time
CU Label It-319	TIA - Cat 6A Channel	✓	-	10.3	✓	05/02/2021 10:05:54
FX Label It-316	GB_T 50312-2016 OF-2000 CH	✓	-	8.48	Overdue!	06/02/2020 09:19:07
FX Label It-317	GB_T 50312-2016 OF-2000 CH	✓	-	8.48	Overdue!	06/02/2020 09:27:05
CU Label It-318	TIA - Cat 6A Channel	✓	-	10.4	✓	05/02/2021 10:03:48
FX Label It-310	GB_T 50312-2016 OF-2000 CH	✗	-	8.48	Overdue!	06/02/2020 08:22:18
CU Label It-357	TIA - Cat 6A Channel	✓	-	10.3	Overdue!	07/02/2021 10:41:01
FX Label It-422	Link Validation	✓	-	8.48	Overdue!	08/02/2021 04:14:32
FX Label It-421	Link Validation	✓	-	8.48	Overdue!	08/02/2021 04:14:19
FX Label It-424	Link Validation	✗	-	8.48	Overdue!	09/02/2021 09:19:14
MPO Label It-411	Custom Limit	✓	-	-		08/02/2021 02:13:34
MPO Label It-412	Custom Limit	✓	-	-		08/02/2021 02:13:40
MPO Label It-413	Custom Limit	✓	-	-		08/02/2021 02:13:45

Total for Selected Reports	Pass	Fail	Length (m)
CU Copper	3	0	0
FX Fibre	4	2	0
MPO MPO	3	0	0


- Detail – Generates full testing result consisting of all tested parameters, plots, test settings and device information of individual point.

# EXPORTING TEST RESULTS

## Project Management




Typical Copper Certification Report (Detail)



Typical Fibre Certification Report (Detail)

2. Select **[Only selected result(s)]** for selected results or **[All result(s)]** for all results that has been loaded. Click **[OK]** to proceed.
3. Choose directory to save PDF or CSV file, enter file name and click **[Save]** to continue.



### Note

When Saving Phase Data option is enabled in the Lab Options, exported CSV file can be used to generate plots for phase information.

Starting from v8.0, eXport PC software has updated the template for PDF reports. Updates includes various alignments and standardisation, and indicating all non-applicable parameters with a “-“.

Starting from v8.3, the “Factory Calibration Status” of the WireXpert will be indicated on all PDF reports to remind end-users of timely calibration of their devices.

It is recommended to calibrate your WireXpert annually to ensure accurate measurements.